

**INGRAM LITTLE LEAGUE**  
Regular Board Meeting  
Sunday, May 15, 2019 - 6:00 PM  
Ingram Little League Ballpark

Call to Order

No actions to be taken.

Review of Fields Upgrades.

General Discussion: (old or new business)

Adjournment

**Intro**

**Ingram LL - Planned Field Improvements**

Following are the planned improvements to the facilities at Ingram Little League.

These improvements should provide a safe and functional playing area for the children and volunteers.

It is important that improvements to the facility (including the fields) are done in a planned manner. Doing so gives the Facilities and Maintenance Manager goals to plan for personnel and materials as well as accomplish these improvements, whenever possible, around events scheduled at the complex.

All Ingram Little League Members are welcome to recommend improvements or needed maintenance, but must present them to the Facilities and Maintenance Manager for approval. Board approval is required if expenses exceed approved budget amounts.

Budgets are approved every year in October (latest November). Therefore, the latest for all recommended improvements, along with estimated costs, need to be presented to the Board by the September Board meeting.

# ILL 2019 Field Improvements.xls

5/12/19

## Summary

General:	\$0.00
Concessions:	\$0.00
Restrooms:	\$0.00
Light Room:	\$0.00
Upstairs:	\$0.00
Equipment Room:	\$0.00
Maintenance Shed:	\$0.00
Storage Shed:	\$0.00
Batting Cages:	\$0.00
Practice Fields:	\$500.00
Pump House:	\$0.00
Parking Area:	\$0.00
Winston Park:	\$0.00

Field 1:	\$3,670.00
Field 2:	\$380.00
Field 3:	\$260.00
	<u><u>\$4,810.00</u></u>

## Field 1

**FIELD 1**

This field was rebuilt three years ago to meet Intermediate play requirements. Those improvements included:

- 1 Skinned area was deepened
- 2 Additional base anchors added at seventy feet
- 3 Grass area edges groomed
- 4 Irrigation heads moved to edge of skinned area
- 5 Home plate re-aligned
- 6 Permanent pitcher's plate added at fifty feet
- 7 Removable pitcher's plate added at forty-six feet
- 8 Diamond Dandy sand added
- 9 Slats added to outfield fence
- 10 Foul poles replaced
- 11 Mower access gate replaced

**Improvements planned for this field include:****ESTIMATE**

1 Groom grass edges for tournament play - 5/09	\$300.00
2 Add Diamond Dandy sand as needed due to grooming - TBD	\$780.00
3 Cut ridges off grass edges of skinned area - August 2019	\$1,000.00
4 Add sod to base paths - July 2019	\$1,500.00
5 Add concrete to dugout ramps (4)	\$30.00
6 Have visitor dugout gate re-sized	\$60.00
7 Re-work visitor dugout bench (raise up)	\$0.00

TOTAL ESTIMATE: \$3,670.00

## Field 2

**FIELD 2**

This field was rebuilt three years ago to meet UIL play requirements from backstop to home plate. Those improvements included:

- 1 Grass removed from infield playing area
- 2 All bases moved and recentered
- 3 Irrigation heads moved to edge of skinned area
- 4 Irrigation heads added behind pitcher's plate and home plate
- 5 Outfield fence replaced and slats added
- 6 Foul poles replaced
- 7 Mower access gate replaced

**Improvements planned for this field include:****ESTIMATE**

1 Groom grass edges for tournament play - TBD	\$150.00
2 Add Diamond Dandy sand as needed due to grooming - TBD	\$120.00
3 Add irrigation box around head behind pitcher's plate - TBD	\$50.00
4 Add concrete to dugout ramps (4) - TBD	\$60.00
5 Re-work visitor dugout bench (raise up) - TBD	\$0.00

TOTAL ESTIMATE: \$380.00

## Field 3

**FIELD 3**

This field has needed minimal improvements over the past three years. This season's improvement included:

- 1 Skinned area re-configured (bases skinned only - no infield)
- 2 Outfield fence replaced and slats added
- 3 Concrete added to dugout floors
- 4 Added electric outlet to backstop
- 5 Concrete slabs added for seating areas
- 6 Rock wall added behind backstop

**Improvements planned for this field include:****ESTIMATE**

- |  |          |
|--|----------|
| 1 Till infield areas as needed. Add mulch, seed with bermuda - TBD | \$200.00 |
| 2 Add Diamond Dandy sand as needed to reworked infield - TBD       | \$60.00  |

TOTAL ESTIMATE: \$260.00

## PRACTICE FIELDS

Improvements planned for this facility include:

ESTIMATE

1 Add electricity to sign & backstop

\$500.00

TOTAL ESTIMATE: \$500.00